

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

> JOHN R. BAZA Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Inspection Report

Permit Number:	C0070006		
Inspection Type:	COMPLETE		
Inspection Date:	Wednesday, August 24, 2005		
Start Date/Time:	8/24/2005 9:00:00 AM		
End Date/Time:	8/24/2005 1:00:00 PM		
Last Inspection:	Wednesday, July 27, 2005		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp 87 Deg F InspectionID Report Number: 700

> Accepted by: pgrubaug 9/1/2005

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

8,925.55	Total Permitted		
95.30	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

✓ Federal	Underground
✓ State	Surface
County	Loadout
✓ Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

UPDES Permit UT0023736 inactivated by letter dated November 18, 2004.

Inspector's Signature

Date

Wednesday, August 24, 2005

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070006 Inspection Type: COMPLETE

Inspection Date: Wednesday, August 24, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		~	
2.	Signs and Markers	~		✓	
3.	Topsoil	~			
4.a	Hydrologic Balance: Diversions	~			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	~			
4.d	Hydrologic Balance: Water Monitoring	~		✓	
4.e	Hydrologic Balance: Effluent Limitations	~	~	✓	
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	~			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	✓			
13.	Revegetation	✓			
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.8	a Roads: Construction, Maintenance, Surfacing	~			
16.	o Roads: Drainage Controls	~			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	✓			
20.	Air Quality Permit	✓		✓	
21.	Bonding and Insurance	✓		✓	
22.	Other	✓			

Permit Number: C0070006 Inspection Type: COMPLETE

Inspection Date: Wednesday, August 24, 2005 Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

UPDES Permit UT0023736 inactivated by letter dated November 18, 2004.

The DOGM Permit was effective on 12/29/2003 and expires on 01/27/2007. Other documents include the following:

- -Certificate of Insurance issued 07/30/05 and terminates 07/30/06.
- -Reclamation Agreement is dated July 1999.
- -UPDES Permit UT0023736 inactivated by letter dated November 18, 2004.
- -Air Quality Permit DAQE-886-96 issued 09/20/1996.

Bond is reduced to \$4,677,600 for 93.5 acres (\$3,118,400) retained, by letter dated October 1, 2004 (signed by Lowell Braxton).

Condition (1) of the permit has been met, by letter dated Jan 23, 2004 (signed by Pamela Grubaugh-Littig).

2. Signs and Markers

The ID sign is located at the public access to the permit boundary. Other markers observed during the inspection were in place as required by the coal rules.

4.d Hydrologic Balance: Water Monitoring

Second quarter 2005 water monitoring information has been entered into the EDI website and uploaded. Water monitoring is current.

4.e Hydrologic Balance: Effluent Limitations

UPDES Permit UT0023736 inactivated by letter dated November 18, 2004. The last discharge monitoring reports submitted are for October 2004. Discharge monitoring reports are no longer required, since the permit has been inactivated.

20. Air Quality Permit

The Air Quality Permit DAQE-886-96 was issued on 09/20/1996 and remains in effect.

21. Bonding and Insurance

The bond issued by Travelers Casualty and Surety Company of America, Bond No. 104329368 was ridered to \$3,118,400 (reduced from \$7,796,000 for the Phase I bond release, ridered on November 10, 2004).